



Zone	Locations	Material
Blast Furnace Bosh & Stack	Stack Position 2 & 3	Stackcrete 608, Stackcrete 62M, Stackcrete 18V, Stackcrete 70ABR
	Bosh Position 4	Stackcrete G
Hearth	Tuyere Belt Position 5	STACKCRETE G
	Protective Lining Position 6	L-CAST 418 NTM
Taphole	Monument Position 7	L-CAST 418 NTM
	Taphole Core Position 8	LCAST 133 NTM, V-CAST 133A

